msec mine subsidence ENGINEERING CONSULTANTS

SIMEC

SIMEC Mining:

Tahmoor South Longwalls S1A to S6A

Subsidence Management Plan for potential impacts to No. 3030 Remembrance Drive, Bargo

AUTHORISATION OF MANAGEMENT PLAN

Authorised on behalf of Tahmoor Coal:	
Name: Zina Ainsworth	
Signature:	
Position: Environment and Community Manager	
Date: 10th Feb 2023	

Authorised on behalf of the land owner of No. 3030 Remembrance Drive, Tahmoor:	
Name:	Kevin Hawach
Signature:	
Position:	Land owner
Date:	

Authorised on behalf of Bargo Petroleum lessee:	
Name:	Rahat Iqbal
Signature:	
Position:	Bargo Petroleum
Date:	

DOCUMENT REGISTER

Date	Report No.	Rev	Comments
Feb-23	MSEC1193-13	A	First draft

References:-

AS/NZS ISO 31000:2009 Risk Management – Principles and guidelines

AEC (2022) *Groundwater Monitoring Event (GME) Report, Bargo Petroleum Service Station*, Aurora Environmental Consulting, 9 December 2022.

JMA (2022) *Pre-Mining Inspection Report No. R0784, 3030 Remembrance Driveway*, JMA Solutions, May 2022.

JMA (2022) *Hazard Identification Report: 3030 Remembrance Driveway, Bargo*, JMA Solutions, 20220810-R1, August 2022.

MSIA (2022a) *Workplace Inspection to identify increased risk from Tahmoor Mine Mining Induced Subsidence for Bargo Petroleum*, Mine Safety Institute of Australia, 5 August 2022.

MSIA (2022b) *Workplace Inspection to identify increased risk from Tahmoor Mine Mining Induced Subsidence for Frapen Motorsports, Automotive Repairs*, Mine Safety Institute of Australia, 5 August 2022.

MSIA (2022c) *Workplace Inspection to identify increased risk from Tahmoor Mine Mining Induced Subsidence for Road Tested Spares, Auto Wreckers*, Mine Safety Institute of Australia, 4 August 2022.

MSO (2017) *Managing risks of subsidence – Guide | WHS (Mines and Petroleum Sites) Legislation*, NSW Department of Planning & Environment, Resources Regulator, Mine Safety Operations, February 2017.

MSEC (2022) *Tahmoor South- Longwalls S1A to S6A - Subsidence ground movement predictions and subsidence impact assessments for natural features and surface infrastructure in support of the Extraction Plan Application. (Report No. MSEC1192, Revision A, May 2022)*, prepared by Mine Subsidence Engineering Consultants.

Tahmoor Coal (2022) *Risk Assessment Report – Bargo Petroleum*. Tahmoor South, November 2022.

Tanknology (2022) *Bargo Petroleum, 3030 Remembrance Drive, Tahmoor*, Report No. SO32493, 14 January 2023.

This information has been retracted
- For more information contact Tahmoor Coal

SIMEC
Level 28, 88 Phillip Street,
Sydney NSW 2000
Legal entity name goes here ABN: 00 000 000 000

T: +61 (0) 2 0000 0000
E: xxxxxxx.xxxxxxx@simecgfg.com
simec.com

MEMBER OF GFG ALLIANCE