msec mine subsidence ENGINEERING CONSULTANTS

SIMEC

SIMEC Mining:

Tahmoor South Longwalls S1A to S6A

Subsidence Management Plan for potential impacts to Tahmoor Garden Centre, 3070 Remembrance Drive, Bargo

AUTHORISATION OF MANAGEMENT PLAN

Authorised on behalf of Tahmoor Coal:	
Name:	Zina Ainsworth
Signature:	Zina Ainsworth
Position:	Environment & Community Manager
Date:	24/01/2023

Authorised on behalf of Tahmoor Garden Centre:	
Name:	Stephen Hollingworth
Signature:	S Hollingworth
Position:	Owner/Manager
Date:	7-2-23

DOCUMENT REGISTER

Date	Report No.	Rev	Comments
Jan-23	MSEC1193-15	A	First draft
Jan-23	MSEC1193-15	B	Final

References:-

AS/NZS ISO 31000:2009 Risk Management – Principles and guidelines

JMA (2022) *Pre-Mining Inspection Report No. R0769, 3070 Remembrance Drive, Bargo NSW 2574*, JMA Solutions, March 2022.

JMA (2022) *Hazard Identification Report: 3070 Remembrance Driveway, Bargo*, JMA Solutions, 20220806-R1, August 2022.

MSO (2017) *Managing risks of subsidence – Guide | WHS (Mines and Petroleum Sites) Legislation*, NSW Department of Planning & Environment, Resources Regulator, Mine Safety Operations, February 2017.

MSEC (2022) *Tahmoor South- Longwalls S1A to S6A - Subsidence ground movement predictions and subsidence impact assessments for natural features and surface infrastructure in support of the Extraction Plan Application. (Report No. MSEC1192, Revision A, May 2022)*, prepared by Mine Subsidence Engineering Consultants.

Tahmoor Coal (2021) *Risk Assessment Report – Infrastructure*. Tahmoor South – Extraction Plan Longwalls 101A to 106A, November 2021.

This information has been retracted
- For more information contact Tahmoor Coal

SIMEC
Level 28, 88 Phillip Street,
Sydney NSW 2000
Legal entity name goes here ABN: 00 000 000 000

T: +61 (0) 2 0000 0000
E: xxxxxxx.xxxxxxx@simecgfg.com
simec.com

MEMBER OF GFG ALLIANCE