Tahmoor Coal Pty Ltd (In Liquidation)

Newsletter

Tahmoor South Domain

September 2026 | Newsletter 4

Tahmoor Mine Update

The process for the sale of Tahmoor Mine to Golden M Tahmoor Coal Holdings Pty Ltd continues to move forward, and the steps to obtain required approvals are also advancing. Subject to those approvals, GM3 will operate the mine once the sale is completed, expected in October.

In parallel with that process, GM3 and the Tahmoor Mine management team are working to establish plans for the safe and efficient restart of longwall mining operations. The focus of the restart program at this time is the operational readiness of the mine.

We were pleased to welcome back a number of employees from unpaid leave last week, and they have commenced work as part of the Tahmoor Mine restart program. Their return marks another important step towards restarting operations. GM3 has also released Expressions of Interest for a range of roles at Tahmoor Mine, with opportunities advertised on SEEK and through the GM3 careers website at www.gm3.au/careers/.

Prioritising the re-employment of suitability qualified members of the Tahmoor workforce is an important part of the restart plan. We look forward to welcoming more members of the Tahmoor team back as the restart progresses.

Contact us

Reception: (02) 4640 0100
Email: tahmoorenquiries@tahmoorcolliery.com.au
Web: www.tahmoorcolliery.com.au

Mine Restart Activities

As part of preparations to restart mining operations, machinery and equipment testing will commence onsite over the coming days. Development activities will also commence underground from early next week.

Following approximately 18 months of limited operations and a period of care and maintenance during liquidation, this represents an important step in the process of safely preparing the mine for a return to full operations.

Residents close by may start to notice familiar sounds of conveyor belts and onsite activities recommencing. We appreciate your patience and understanding as we undertake these necessary restart works.

If you have any questions, please feel free to email tahmoorenquiries@tahmoorcolliery.com.au or phone 02 4640 0100.

Monitoring and Inspections

In preparation for Longwall S4A mining as part of the restart program, Tahmoor Mine and its specialist consultants will begin re-establishing inspections and routine monitoring throughout the Tahmoor South area in the coming weeks.

This work will include:

- vegetation clearing for survey monitoring requirements along roads and culverts
- re-establishment of disturbed survey markers
- baseline infrastructure inspections
- rail, road and creek surveys
- property pool gate and dam inspections.

These activities are an important part of the preparations for the safe and responsible recommencement of mining operations and will help ensure key infrastructure and natural features continue to be monitored as the mine restart progresses.

Tahmoor Mine Plan

Figure 1 highlights the location of Longwall S4A in yellow.

- The blue line (predicted 20mm Subsidence Area) indicates the area predicted to experience subsidence from LW S4A mining.
- The grey shading depicts the previously mined areas.



Figure 1 - Longwall South 4A subsidence zone